

1. 측정결과 - 2023. 01. 05.

측정 장비 (종류/수량)	시료번호	측정 지점	유량 (ℓ/분)	측정 일시 (분)	측정 결과 (I/cc)	검출석면의 종류
LX40A / 8대	#1	부지경계선1	9.88	245	0.0022	N/A
	#2	부지경계선2	9.94	245	0.0018	N/A
	#3	부지경계선3	9.95	245	0.0016	N/A
	#4	부지경계선4	9.94	245	0.0020	N/A
	#5	작업장주변	9.93	125	0.0036	N/A
	#6	위생설비입구	9.92	45	0.0026	N/A
	#7	음압기공기배출구	9.93	45	0.0029	N/A
	#8	폐기물반출구	9.91	45	0.0029	N/A
	#9	폐기물보관지점1	9.90	45	0.0029	N/A
	#10	폐기물보관지점2	9.91	45	0.0026	N/A

- 측정시간(시작, 종료)은 측정사진대지 참조.
- 석면안전관리법 시행령 석면배출허용기준 0.01개/cc 이하

2. 측정사진

투입장비 종류 / 수량 LX40A / 8대

측정지점	비산측정 시작 사진	비산측정 종료 사진	결과(I/cc)
부지경계선1	 측정 시작 시간 09:46	 측정 종료 시간 13:51	0.0022
부지경계선2	 측정 시작 시간 09:47	 측정 종료 시간 13:52	0.0018
부지경계선3	 측정 시작 시간 09:48	 측정 종료 시간 13:53	0.0016
부지경계선4	 측정 시작 시간 09:49	 측정 종료 시간 13:54	0.0020
작업장주변	 측정 시작 시간 10:32	 측정 종료 시간 12:37	0.0036

측정지점	비산측정 시작 사진	비산측정 종료 사진	결과(l/cc)
위생설비 입구			0.0026
	측정 시작 시간 09:41	측정 종료 시간 10:26	
음압기공기 배출구			0.0029
	측정 시작 시간 09:44	측정 종료 시간 10:29	
폐기물 반출구			0.0029
	측정 시작 시간 10:46	측정 종료 시간 11:31	
폐기물 보관지점1			0.0029
	측정 시작 시간 11:47	측정 종료 시간 12:32	
폐기물 보관지점2			0.0026
	측정 시작 시간 11:47	측정 종료 시간 12:32	

1. 측정결과 - 2023. 01. 04.

측정 장비 (종류/수량)	시료번호	측정 지점	유량 (ℓ/분)	측정 일시 (분)	측정 결과 (ℓ/cc)	검출석면의 종류
LX40A / 7대	#1	부지경계선1	9.95	245	0.0020	N/A
	#2	부지경계선2	9.90	245	0.0018	N/A
	#3	부지경계선3	9.94	245	0.0016	N/A
	#4	부지경계선4	9.88	245	0.0020	N/A
	#5	작업장주변	9.91	125	0.0032	N/A
	#6	위생설비입구	9.90	45	0.0026	N/A
	#7	음압기공기배출구	9.87	45	0.0033	N/A

- 측정시간(시작, 종료)은 측정사진대지 참조.
- 석면안전관리법 시행령 석면배출허용기준 0.01개/cc 이하

2. 측정사진

투입장비 종류 / 수량 LX40A / 7대

측정지점	비산측정 시작 사진	비산측정 종료 사진	결과(t/cc)
부지경계선1			0.0020
	측정 시작 시간 10:06	측정 종료 시간 14:11	
부지경계선2			0.0018
	측정 시작 시간 10:07	측정 종료 시간 14:12	
부지경계선3			0.0016
	측정 시작 시간 10:08	측정 종료 시간 14:13	
부지경계선4			0.0020
	측정 시작 시간 10:10	측정 종료 시간 14:15	
작업장주변			0.0032
	측정 시작 시간 10:26	측정 종료 시간 12:31	

측정자점	비산측정 시작 사진	비산측정 종료 사진	결과(l/cc)
위생설비 입구			0.0026
	측정 시작 시간 10:18	측정 종료 시간 11:03	
응압기공기 배출구			0.0033
	측정 시작 시간 10:20	측정 종료 시간 11:05	